



rs 11 Chart I

Psychrometric Chart - Low Temperatures
(from Industrial Ventilation)



PSYCHROMETRIC CHART HIGH TEMPERATURES Barometric Pressure 29.92 In. Hg



AS HANDED IN U.S.A.

COPIED BY 1946 CLARK ET CORPORATION

rs 12 Chart 2

Psychrometric Chart - High Temperatures
(from Industrial Ventilation)